

R07	L	D	E	R	T
B	110	40	20	40	300
C	130	50	20	5	300
D	100	45	15	10	400
D1	88	45	15	5	340
E	110	45	18	10	270
F	105	50	18	10	420
G	102	45	14	8	350
Q	130	45	15	5	340
Q3	105	45	15	5	340
Q4	120	45	15	5	340