

R01-1	L	D	E	R	D1
A	127	45	15	5	25
A1	138	60	20	6	28
C	105	50	18	10	25
D	102	45	14	7	15
E	100	45	15	10	19
E1	100	45	15	10	16
E2	100	45	15	10	20
F	110	45	18	7,5	16
G	78	35	12	5	15
I	130	50	20	10	20
J	130	40	20	40	25
K	115	50	15	5	20
M	85	30	12	4	10
O	110	40	20	7,5	20
P	152	70	25	8	28
Q	130	45	15	10	25
V	150	60	20	6	28
W	102	44	15	5	22
Z	90	40	14	5	15