

R06	L	D	E	R	T
A	110	40	20	40	300
B	130	50	20	40	400
C	100	45	15	5	373
C1	105	50	18	10	370
D	102	45	14	10	380
E	78	35	12	7	450
F	127	45	15	5	400
F1	104	45	15	5	390
I	130	50	20	10	450
V	150	60	20	6	400