

R11	L	L1	E	E1
A	89	84,4	10	2
A1	50	40	30	20
A2	80	73	15	8
B	60	54	10	4
C	107	97	20	10
D	85	75	15	5
D1	55	45	15	5
E	65	50	20	5
E1	65	50	20	5
F	105	95	20	5
G	200	190	20	10
G1	90	80	20	10
G2	20	10	20	10
H	85	75	28	20
I	105	100	20	15
J	98	80	25	4
K	90	74	25	5
L	95	85	20	10
M	20	19	15	14
N	70	60	15	5
O	65	58	12	5
P	90	74	25	5
Q	125	105	30	10
R	85	73	30	18
S	94	84	20	10
T	101	91	20	14,23
U	85	75	20	10
V	65	55	15	5
X	90	75	20	5
W	64	59	10	5
Z	140	130	20	10